



2009219

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. UTR 000 000 661		Manifest Document No. 040525		2. Page 1 of 1	
3. Generator's Name and Mailing Address USEPA REGION 8 999 18th ST. SUITE 300 DENVER, CO. 80202-2466							
4. Generator's Phone (303) 312-6983 ATTN: FLOYD NICHOLS							
5. Transporter 1 Company Name MP ENVIRONMENTAL		6. US EPA ID Number CAT 000 624 247		A. State Transporter's ID N/A			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 877-800-5111			
				C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address CLEAN HARBORS GRASSY MOUNTAIN FACILITY 3 MILES EAST 7 MILES NORTH OF EXIT 41 OFF I-80 CLINE, UT 84043				10. US EPA ID Number UTD 971 301 748		E. State Facility's ID	
						F. Facility's Phone 801 323-8100	
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No. Type		Unit	
a. 1 KQ' ASBESTOS, 9, NA 2212, PG III				COI CM		00025 CY	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11A) CH 65634B 25 YD ROLL OFF (ASBESTOS CONTAMINATED PRE + DEBRIS DOUBLE BAGGED + IDENTIFIED) SALES ORDER: D979C828				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information USE STANDARD PROTECTIVE EQUIPMENT + CLOTHING (EMERGENCY # (888) 814 7477 24 HR.)							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Floyd N. Nichols, OSC				Signature Floyd N. Nichols		Date 5/25/04	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature Richard Boggs		Date 5/25/04	
Printed/Typed Name RICHARD BOGGS				Signature		Date	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date	

NON-HAZARDOUS WASTE

TRANSPORTER

FACILITY

